Installation

NetBotz Door Switch Sensor (NBES0303S) for NS WX Cabinet With Swing Handle

Inventory





Screw, M3 X 10 TORX for cabinet frame (2)

Screw, M4 X 10 Pan head for cabinet door (2)



Sensor bracket for cabinet frame (1)



M3 hex nut (4)



Adhesive cable tie holder (5)

Magnet bracket for cabinet

door (1)



RJ-45 coupler (1)

203 mm (8 in) cable tie

(10)

4.57 m (15 ft) cable for sensor (1)

63.5-mm (2.5-in) dual adhesive tape (4)

Screw, 6-32 x 5/16 in (6, not used)

APC by Schneider Electric 70 Mechanic Street Foxboro, MA 02035 USA

As standards, specifications, and design change from time to time, please ask for confirmation of the information given in this publication. © 2021 - APC by Schneider Electric. All rights reserved.



Install the Door Magnet

Secure the magnet to the door with M4 X 10 Pan head screws. Torque the screws 5 N•m (3.69 ft•lb).



Install the Sensor

Secure the sensor to the cabinet frame with M3 X 10 TORX screws. Torque the screws 5 N•m (3.69 ft•lb).



Connect the Sensor

Connect the sensor cable to the appropriate port on your NetBotz appliance (see your appliance documentation for details about ports. You can use the RJ-45 coupler to extend the sensor cable to up to 30.5 m (100 ft) with standard CAT-5 cabling (not provided).

If needed, you can use the adhesive tape, adhesive cable tie holders, and cable ties to manage your cables.

The 6-32 x 5/16 in screws are not used.